


BUILDING SAFETY CERTIFICATE

Certified that the existing building Dr. D.Y.Patil Education and Research Foundation, Survey No.9/1, City Survey No. 218, Nigdi, 411044 is having blocks / Floors as per details below.

Detail Blocks in School	Block (1)
No. of Floors in the Block	Basement+Ground Floor + 6 Floors

The building is occupied by D.Y. Patil World School, Survey No.9/1, City Survey No. 218, Nigdi, 411044 have complied with the Building safety requirements and verified by the officers concerned of Public Works Department, Pune on 10/01/2025 in the presence of Principal Mrs. Kshitija Misal, D. Y. Patil World School, Survey No.9/1, City Survey No. 218, Nigdi, 411044 and that the building is structurally safe based on the structural stability certificate attached in the proposal and fit for occupancy for a period of 1 year.

Issued on 06 /03 /2025 at Pune by



(S. A. Kotkar)
Sub Divisional Engineer
P. W. Sub Division No 5,
Pune 411001.



OW.No./ DB / NOC / 1999/2025
Office of the Executive Engineer,
Public Works Division, Pune-01.

Date :- 6 MAR 2025

'Countersigned'


(Dr. S. R. Katkar)
Executive Engineer,
Public Works Division,
Pune-411001.

Copy to :- 1. D.Y. Patil World School, Survey No.9/1, City Survey No. 218, Nigdi, 411044
2. Sub Divisional Engineer, P. W. Sub Division No 5, Pune 411001.